

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
Company	Steve Demczak				
Company	Dennis Ware				

Inspection Report

Permit Number:	C0070038			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, March 23, 2011			
Start Date/Time:	3/23/2011 2:00:00 PM			
End Date/Time:	3/23/2011 4:00:00 PM			
Last Inspection:	Thursday, February 17, 2011			

Inspector: Steve Demczak,

Weather: Cloudy, Partly Snow Covered, 30's

InspectionID Report Number: 2694

Types of Operations

Reprocessing

Accepted by: jhelfric 4/4/2011

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

14,662.49 Total Permit	tted		
71.44 Total Distur	Total Disturbed		
125.41 Phase I			
92.45 Phase II			
92.45 Phase III			

Mineral Ownership

✓ Other

✓ Federal
✓ Underground

State
Surface

County
✓ Loadout

✓ Fee
Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Stephen J. Denyk Steve Demozak,

Date



OIL, GAS & MINING

Inspector ID Number: 39

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 23, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		V	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		Y	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	~		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.1	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 23, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit will expire on April 24, 2011. The the Division is in the process of renewing the permit.

2. Signs and Markers

The identification signs is next to the road to the property. The information meets the R645 Coal Rules.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The diversions were opened and functioning as designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclaimed area is pocked for sediment control.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile has been reclaimed and the permittee received approval for no more quarterly inspection.

8. Noncoal Waste

The site is clear of non-coal waste material.

9. Protection of Fish, Wildlife and Related Environmental Issues

There are signs that deer have been feeding on the reclaimed site. This is located next to the Price River. There are elk throughout Crandall Conyon.

12. Backfilling And Grading

The total disturbed area is reclaimed and is backfilled and graded.

18. Support Facilities, Utility Installations

There are no facilities.